

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter Division Director 1594 West North Temple, Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

April 22, 1997

TO:

Board of Oil, Gas and Mining

THRU:

Mary Ann Wright, Associate Director

THRU:

D. Wayne Hedberg, Permit Supervisor

FROM:

Tom Munson, Senior Reclamation Specialist

RE:

Updated Information, Centurion Mines Corporation, OK Mine, M/001/039, Beaver

County, Utah

It has come to our attention that the legal description as found in the Reclamation Contract and the executive summary are not the same. We contacted Centurion Mines Corporation in order to clarify this discrepancy and obtain the corrected legal description. We asked Centurion Mines to address the legal description for each phase of their mining operation.

Enclosed you will find: 1) an updated executive summary; 2) updated page 8 of the Reclamation Contract which shows the legal description for each phase of the project; and 3) a map showing the three phases of their operation.

As stated in our previous memo, Centurion Mines only wishes to post reclamation surety for Phase I of their project at this time, although the Division has approved of the mining and reclamation permit for the entire project. At such time as Phase II and Phase III are initiated, Centurion Mines will again have to come before the Board to seek approval of the form and amount of additional surety.

jb
Enclosure: Updated Executive Summary, page 8 of the MR-RC, Map o:\board\M001039.mem

## **EXECUTIVE SUMMARY**

Prepared January 8, 1997 Updated April 22, 1997

Mine Name: OK Mine	I.D. No.: M/001/039	
Operator: Centurion Mines Corporation	County: Beaver	
331 South Rio Grande Street - Suite 201	New/Existing: New	
Salt Lake City, Utah 84110	Mineral Ownership: Fee	
	Surface Ownership: Fee	
Telephone: (801) 534-1120	Lease No.(s): N/A	
Contact Person: Rick Havenstrite	Permit Term: Life of Mine	
A STATE OF THE STA		
Life of Mine: 10 years +		
Legal Description: Phase I: NE1/4 and SE1/4 of the NW		
7; the SE1/4 and the NE1/4 of the SW1/4; the NW1/4 and	the SW1/4 of the SE1/4 of Section 6, T27S, R11W,	
SLB&M, Beaver County, Utah		
Phase II: NW1/4 and SW1/4 of the SE1/4 of Section 6; the	ne NW1/4 of the NE1/4 of Section 7, T27S, R11W,	
SLB&M, Beaver County, Utah		
Phase III: NE1/4 and SE1/4 of the SE1/4 of Section 6; the		
SW1/4 of Section 5; the NW1/4 of the NW1/4 of Section	8; the NW1/4 and NE1/4 of the NE1/4 of Section 7,	
T27S, R11W, SLB&M, Beaver County, Utah		
Mineral(s) to be Mined: Copper produced from the foll	owing oxide copper minerals - azurite, malachite and	
tenorite		
Acres to be Disturbed: 275 acres for Phases I, II & III,	$\frac{1}{1}$ (Phase I = 128 acres)	
Present Land Use: <u>Hunting, grazing, rock collecting, or</u>	ff-road vehicles	
Postmining Land Use: <u>Grazing and recreation</u>		
Variances from Reclamation Standards (Rule R647) G		
impoundments; 111-12-topsoil redistribution (pit walls)		
(1) pit highwalls will be allowed to remain at angles steep		
flattening the pit walls at the end of mining would have the	e effect of making the remaining ore uneconomic for	
future mining. The current pit walls are stable at approximately	mately 60 degrees and have been for 25 years.	
2) dams & impoundments: A small impoundment of less	s than several hundred square feet will be left based	
on the following facts. It will have a reduced drainage are		
stabilized with coarse rock to prevent failure. It will also		
wildlife following reclamation. It is not considered large		
overall benefit to an arid environment.	v v	
3) topsoil redistribution and revegetation: It is not prac	tical to regrade or revegetate pit walls. The pit walls	
will be left at approximately 55 degrees. The walls will be solid rock. Based on the condition of the current		
pit, it is highly unlikely that vegetation can be established		
part of the control o		

Page 2 Executive Summary M/001/039

## Soils and Geology

maintained outside the fenced area.

Soil Description: Soils are all derived from decomposed granite with varied amounts of silt, sand and rocks. Soil depths in the mine and dump areas are typically less than 5 feet and are underlain by bedrock. In the area of the pad, soils contain a higher degree of silt and sand and the depth to bedrock is 5 to 20 feet typically.

<b>pH</b> : _8.1 - 8.3
pri. <u>0.1 - 0.5</u>
Special Handling Problems: None
Geology Description: The project is located in low foothills and the top of a gently southernly sloping alluvial
fan. The entire area is underlain by a massive igneous (granite) intrusion. A nearly vertical fault zone cut the
granitic formation and this fault was later mineralized with copper minerals such as azurite, malachite, and
tenorite. The relatively homogenous granitic rock formation extends at least 3 miles in every direction.
<u>Hydrology</u>
Ground Water Description: There have been hundreds of holes drilled in the vicinity of the project. The holes drilled in the vicinity of the pit, 400 feet below the bottom of the pit, were dry. Other holes drilled within the vicinity of the project encountered minor amounts of brackish water. Only several holes encountered any significant water and these holes were located next to one of the two main drainages coming from the hills above the project. Hole MD-1 was drilled in the vicinity of the pad to a depth of 705 feet and encountered negligible water. Hole MW-1, southwest side of the pad, encountered good water and is down gradient of the pad and is to remain a monitoring well.
Surface Water Description: There are no streams or springs within 5 miles of the operation. A major wash
exists to the west of the project which collects surface runoff from a large area to the west and north of the
project. This wash is ephemeral and will not be disturbed. It and only experiences flows during extremely
intense storms.
Water Monitoring Plan: Groundwater will be monitored for 8 consecutive months prior to the commencement of operation and semi-annually thereafter. Two current groundwater monitoring wells have been located immediately down gradient (south) of the proposed heap leach pad and processing ponds area.
Ecology
Vegetation Type(s); Dominant Species: Big sagebrush, rabbitbrush, squirreltail grass, indian ricegrass
Percent Surrounding Vegetative Cover: 21%
Wildlife Concerns: Only concern are the antelope. Centurion intends to construct a six foot high chain link

fence around the heap leach pad and processing plant area. In addition, a water trough will be placed and

## ATTACHMENT "A"

Centurion Mines Corporation	OK Mine	
Operator	Mine Name	
M/001/039	Beaver	County, Utah
Permit Number		oddiney/ otali

## The legal description of lands to be disturbed is:

**Phase I**: NE1/4 and SE1/4 of the NW1/4; the NW1/4 and SW1/4 of the NE1/4 of Section 7; the SE1/4 and the NE1/4 of the SW1/4; the NW1/4 and the SW1/4 of the SE1/4 of Section 6, T27S, R11W, SLB&M, Beaver County, Utah

**Phase II:** NW1/4 and SW1/4 of the SE1/4 of Section 6; the NW1/4 of the NE1/4 of Section 7, T27S, R11W, SLB&M, Beaver County, Utah

**Phase III**: NE1/4 and SE1/4 of the SE1/4 of Section 6; the NW1/4 and SW1/4 of the SW1/4; the SE1/4 of the SW1/4 of Section 5; the NW1/4 of the NW1/4 of Section 8; the NW1/4 and NE1/4 of the NE1/4 of Section 7, T27S, R11W, SLB&M, Beaver County, Utah



